

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number 30800	2. Page 1 of 1	3. Emergency Response Phone 214-789-1627	4. Manifest Tracking Number <b>013487470 JJK</b>	
5. Generator's Name and Mailing Address US EPA REGION 6-CES ENVIRONMENTAL 1445 ROSS AVE, SUITE 1200 ATTN: GARY MOORE DALLAS, TX 75202 214-789-1627			Generator's Site Address (if different than mailing address) US EPA REGION 6-CES ENVIRONMENTAL 4804 GRIGGS RD Houston, Texas 77021			
Generator's Phone:			U.S. EPA ID Number			
6. Transporter 1 Company Name CKG Services			U.S. EPA ID Number TXR000079159			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Blue Ridge Landfill Permit #89429 2200 FM 521 Fresno, Texas 281.835.8142			U.S. EPA ID Number SWR #89429			
Facility's Phone:						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
1.	NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATION	001 TIA	5000	GL	FXSF-207-1	
2.						
3.						
4.						
14. Special Handling Instructions and Additional Information REPUBLIC WASTE APPROVAL #51121419794 132 VB607 FT506 CUSTOMER # 333354						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name GARY MOORE FOR EPA			Signature [Signature]		Month Day Year 12/15/2014	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Justin Watson			Signature [Signature]		Month Day Year 12/15/14	
Transporter 2 Printed/Typed Name			Signature		Month Day Year	
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
Manifest Reference Number:						
18b. Alternate Facility (or Generator)						
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. 2. 3.						
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name			Signature		Month Day Year 12/15/14	

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>30900</b>		2. Page 1 of <b>1</b>		3. Emergency Response Phone <b>214-789-1627</b>		4. Manifest Tracking Number <b>013487478 JJK</b>			
		5. Generator's Name and Mailing Address <b>US EPA REGION 8-CES ENVIRONMENTAL 1445 ROSS AVE, SUITE 1200 ATTN: GARY MOORE DALLAS, TX 75202 214-789-1627</b>						Generator's Site Address (if different than mailing address) <b>US EPA REGION 8-CES ENVIRONMENTAL 4904 GRIGGS RD Houston, Texas 77021</b>			
6. Transporter 1 Company Name <b>CKG Services</b>		U.S. EPA ID Number <b>TXR00079159</b>									
7. Transporter 2 Company Name		U.S. EPA ID Number									
8. Designated Facility Name and Site Address <b>Blue Ridge Landfill Permit #89429 2200 FM 521 Fresno, Texas 261.835.6142</b>		U.S. EPA ID Number <b>SWR #89429</b>									
Facility's Phone:											
<b>GENERATOR</b>	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	1.	<b>NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATION</b>				<b>001</b>		<b>EST 5,000</b>	<b>GL</b>	<b>FXNF 207.1</b>	
	2.										
	3.										
	4.										
14. Special Handling Instructions and Additional Information <b>REPUBLIC WASTE APPROVAL #51121419794 CUSTOMER # 333354 132 VB 007, PFS06</b>											
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
Generator's/Offor's Printed/Typed Name <b>GARY MOORE for EPA</b>						Signature <i>[Signature]</i>		Month Day Year <b>12 16 2014</b>			
<b>INT'L</b>	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____										
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name <b>Justin Watson</b> Signature <i>[Signature]</i> Month Day Year <b>12 16 14</b> Transporter 2 Printed/Typed Name _____ Signature <i>[Signature]</i> Month Day Year _____										
<b>TRANSPORTER</b>	18. Discrepancy										
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection										
	18b. Alternate Facility (or Generator) _____ Manifest Reference Number: _____ U.S. EPA ID Number _____										
	Facility's Phone: _____										
<b>DESIGNATED FACILITY</b>	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____										
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. _____ 2. _____ 3. _____										
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name <i>[Signature]</i> Signature <i>[Signature]</i> Month Day Year <b>12 16 14</b>										

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>30900</b>		2. Page 1 of <b>1</b>		3. Emergency Response Phone <b>214-789-1627</b>		4. Manifest Tracking Number <b>013487479 JJK</b>	
		5. Generator's Name and Mailing Address <b>US EPA REGION 6-CES ENVIRONMENTAL 1445 ROSS AVE, SUITE 1200 ATTN: GARY MOORE DALLAS, TX 75202 214-789-1627</b>						Generator's Site Address (if different than mailing address) <b>US EPA REGION 6-CES ENVIRONMENTAL 4904 GRIGGS RD Houston, Texas 77021</b>	
6. Transporter 1 Company Name <b>CKG Services</b>		U.S. EPA ID Number <b>TXR 000079159</b>		7. Transporter 2 Company Name		U.S. EPA ID Number			
8. Designated Facility Name and Site Address <b>Blue Ridge Landfill Permit #89429 2200 FM 521 Fresno, Texas 281.635.6142</b>		U.S. EPA ID Number <b>SWR #89429</b>		Facility's Phone:					
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))			10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
1.	<b>NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATION</b>			<b>001</b> <b>TI</b>		<b>200</b>	<b>GL</b>	<b>EXCF-207-1</b>	
2.									
3.									
4.									
14. Special Handling Instructions and Additional Information <b>REPUBLIC WASTE APPROVAL #51121419794 132 VB 607 CUSTOMER # 333354</b>									
15. <b>GENERATOR'S/OFFEROR'S CERTIFICATION:</b> I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name <b>GARY MOORE for EEA</b>				Signature <i>[Signature]</i>		Month Day Year <b>12/16/2014</b>			
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____									
17. Transporter Acknowledgment of Receipt of Materials									
Transporter 1 Printed/Typed Name <b>Justin Watson</b>				Signature <i>[Signature]</i>		Month Day Year <b>12/16/14</b>			
Transporter 2 Printed/Typed Name				Signature		Month Day Year			
18. Discrepancy									
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection <b>Blue Ridge 12:35 307626</b>									
18b. Alternate Facility (or Generator) Manifest Reference Number: _____ U.S. EPA ID Number: _____ <b>2200 FM 521 (PO Box 879) Fresno, Texas 77545</b>									
18c. Signature of Alternate Facility (or Generator) Month Day Year <b>DEC 16 2014</b>									
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)									
1.		2.		3.					
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in item 18a									
Printed/Typed Name <i>[Signature]</i>				Signature <i>[Signature]</i>		Month Day Year <b>12/16/14</b>			

### GENERATOR

INT'L

TRANSPORTER

DESIGNATED FACILITY